

[Super4USB Relay module support software](#)

Situation	TCTEC Software used
MS Windows, Dot NET	tctecUSB4.dll
MS Windows, C, Pascal, C++, delphi	Super4.dll
Linux, C, C++	Irelayset
MS Windows, Labview	Relayset.exe, and provided vi
Linux, Labview	Lrelayset
National Instruments TestStand	Relayset.exe, or Super4USB.dll (dot Net dll)
Change relay board name or test relay boards,	RelayManager for MS windows.
Update relay board firmware	Mprog 3.0a (FTDI application)